


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-130	Smoke	10/21/2008	ADS/TM	S09MM_001MH	Dry	Yes	1,817.24



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-130	Smoke	10/21/2008	ADS/TM	S09MM_001MH	Dry	Yes	1,817.24

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09MM_003G2	S09MM_003MH	S09MM_008MH	250.5917	8
S09MM_010G1	S09MM_010MH	S09MM_003MH	46.58288	8
S09MM_003G1	S09MM_003MH	S09OO_028MH	213.8531	8
S09MM_014G1	S09MM_014MH	S09MM_003MH	238.4905	8
S09MM_018G1	S09MM_018DE	S09MM_001MH	363.1476	8
S09OO_011G1	S09OO_011MH	S09MM_005MH	310.4370	8
S09MM_001G1	S09MM_001MH	S09MM_010MH	155.5726	8
S09MM_005G1	S09MM_005MH	S09MM_014MH	238.5681	8

Observations & Photos

Obs_ID S1028-130-OB01

Address 2307 Garrison Blvd

Status Private

Source Cleanout

Location Yard - back

Nearest MH S09OO_011MH

Comments Smoke from cleanout in back yard. 2307 Garrison Blvd.



Picture \S1028-130-OB01-P01.jpg

Comments Back of house, 2307 Garrison Blvd.